Whitney

Complete Power Up Procedure on 160/180i Series Controls

- 1. Perform any external procedures (drain air compressor, start dryer, etc.)
- 2. Perform preventative maintenance as per Whitney daily checklist
- 3. Ensure main power at power island is on
- 4. Ensure air is provided to system
- 5. Ensure gases for cutting are turned on
- 6. Press **On** button on operators panel. Wait for logon screen to appear
- 7. Older NT controls will prompt for a password. If not prompted proceed to step 8.

Туре	USER NAME:	Operator
	PASSWORD:	3700FR for a 3700 fixed ram machine
		3700RR for a 3700 rotary ram machine
		4400 for a 4400 MAX
		3400 for a 3400 RTC

then press Enter

- 8. Wait for Position screen to appear (black with yellow numbers)
- 9. Turn Emergency Stop key clockwise to release
- 10. Press **Oper Ack** three times slowly (1 second between presses)
- 11. Press Hyd On/Off on operator's panel
- 12. Press **Mem** hardkey
- 13. Press **Prog** hardkey
- 14. Type in **O9100**
- 15. Press **O SRH** softkey

OP-002-All-1680I-A-Power Up Procedure

Whitney

16. Press Cycle Start on operator's panel

Note: If machine does not move, a message will inform you of the problem. Press **Message** hardkey to see current messages. Press **Oper Ack** to clear messages once stated problem has been corrected. The 9100 message **cannot** be cleared with **Oper Ack**. Press **Cycle Start** after clearing all messages possible to run 9100 and clear this message.

- 17. Turn on torch by pressing the green button labeled "Torch On" until it stays lit. This may take up to 5 seconds with a HT2000 torch. HPR users skip to step 22.Note: If button will not stay lit, refer to status lights on front of torch power pack for problem.
- 18. Avoiding the safety barrier, move the gas switch to "Test Preflow" and verify settings. Adjust as necessary.
- 19. Move the switch to "Run" and let balls settle.
- 20. Move the switch to "Test Cutflow" and verify settings. Adjust as necessary.
- 21. Move the switch to "Run" and let balls settle.
- 22. Power up is complete. Load programs, tooling, and/or torch consumables as required and proceed with machine operation.

Note: This is a base procedure for reference only. Slight modifications may be necessary to conform to customer policies. Steps may change dependant upon problems and/or errors during execution as well as familiarity with system over time.

OP-002-All-1680I-A-Power Up Procedure