## Loading a Program From Disk or Computer

- 1. Press **Func** and **Prgm** keys on MDI panel simultaneously to switch to Program screen if needed
- 2. Press Edit key on operators panel
- 3. Press Read softkey
- 4. Perform necessary steps to send file from computer or external disk

## Loading a Program From Memory

- 1. Press **Func** and **Prgm** keys on MDI panel simultaneously to switch to Program screen if needed
- 2. Press Edit key on operators panel
- 3. Type letter **O** and program number desired (Example **O1234**)
- 4. Press **down cursor** key (Opr Alarm button WITHOUT Func)

## **Checking Inputs & Outputs in Diagnostics**

- 1. Press **Func** and **Dgnos** keys on MDI panel simultaneously 3 times (until DIAGNOSTICS is displayed in the lower right window)
- 2. To find a value, type **N** then the diagnostic number (Ex. **N14**)

**Note:** When searching for values over 1000, add 2000 to the value. Example: X1002.1 is actually X3002.1

Common diagnostics to check:

- 6.2 Stripper Sensor 6.4 Die Sensor
- 6.3 Punch Sensor 2.4 Die Successfully Removed (photo switch over bolster plate)

14.5	Arm 1 Extend	14.6	Arm 2 Extend
17.5	Arm 1 Retract	14.7	Arm 2 Retract

Refer to machine electrical prints for a complete list of diagnostics

## Changing tools in MDI

- 1. Press **Func** and **Prgm** keys on MDI panel simultaneously to switch to Program screen if needed
- 2. Press **MDI** key on operators panel
- 3. Press Next softkey (MDI screen must be in Next, not Current)
- Type in **T#** (inserting the desired tool) to fetch the tool **IF** the tool is not already in the standby arm Example **T203**
- 5. Press **Input** on operators panel
- 6. Press Cycle Start
- 7. Type in **Y-63.5** on MDI panel
- 8. Press **Input** on operators panel
- 9. Press Cycle Start
- 10. Type in **T#** from step 4 on MDI panel
- 11. Press Input on operators panel
- 12. Type in **M06** on MDI panel
- 13. Press Input on operators panel
- 14. Press Cycle Start

End of Procedure